

# View Building


Account: **Energy Savers**

[+ Building Information](#)

[⊖ Expand](#)






## Mould Risk

Filter:

 Pick date range...

**17 January - 07 February 2023**




-  75-100 Very High
-  50-75 High
-  25-50 Medium
-  1-25 Low
-  0 Very Low



### Low Risk

You should be aware of a possible mould risk in this room.

**Overall Risk Score**



Avas Room

[View Room](#)



Back Lounge

[View Room](#)



Harrys Room

[View Room](#)



Kitchen

[View Room](#)



Mikes Room

[View Room](#)



Playroom

[View Room](#)

## Average Building Conditions

INTERNAL  
TEMPERATURE

**18.9 °C**

INTERNAL HUMIDITY

**49.9 % RH**

EXTERNAL  
TEMPERATURE

**4.2 °C**

TEMPERATURE  
DIFFERENCE

**+14.8 °C**

 Export result

 Upload Data

© Build Test Solutions Ltd.